

Information pursuant to Art. 33 of UK REACH Regulation	
According to Art. 33 of the UK REACH Regulation (Regulation (EC) No. 1907/2006), there are information obligations for suppliers of articles containing so-called substances of very high concern (SVHC) in a concentration of more than 0.1 % weight by weight. The Health and Safety Executive (HSE) has published an overview of all substances included in the REACH Candidate List on its website: UK-REACH Candidate List. Sustainability is an integral part of Porsche's strategy. Our goal is to use sustainable concepts and materials along all supply chains and to constantly expand their scope and to use substances that are subject to Art. 33 of the REACH Regulation only where they are indispensable for technical reasons. If our vehicles and products contain substances in accordance with Art. 33 of the REACH Regulation, their release is limited to a minimum when handled as intended. The intended handling of our vehicles and products is described in the respective operating instructions. The disposal of vehicles and vehicle parts should always be carried out taking into account the regionally applicable legal requirements.	
Model: E3PA (Nov. 2024)	
The CAS number after the substance name in brackets allows a clear assignment of the substance based on the CAS database.	
Vehicle Area	Substance Name (CAS No.)
Interior	
Instrument Panel & Console; Side Mirror	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol (3147-75-9); 4,4'-Isopropylidenediphenol (80-05-7); Bis(alpha,alpha-dimethylbenzyl) peroxide (80-43-3); Bumetrizole (3896-11-5); Diboron-trioxide (1303-86-2); Dioctyltin dilaurate (3648-18-8); Lead (7439-92-1); Lead titanium zirconium oxide (12626-81-2); Lead-monoxide (1317-36-8); Lead-titanium-trioxide (12060-00-3); Melamine (108-78-1); N,N-Dimethylacetamide (127-19-5); Octamethylcyclotetrasiloxane (556-67-2)
Steering wheel	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol (3147-75-9); 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol (119-47-1); Lead (7439-92-1); Lead-monoxide (1317-36-8)
Seats & Safety Belts	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol (3147-75-9); 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol (25973-55-1); 2-Methylimidazole (693-98-1); Bis(2-(2-methoxyethoxy)ethyl)ether (143-24-8); C,C'-azodi(formamide) (123-77-3); Dioctyltin dilaurate (3648-18-8); Lead (7439-92-1); Lead-monoxide (1317-36-8); Melamine (108-78-1); Sodium borate, decahydrate (1303-96-4); Triphenyl-phosphate (115-86-6)
Interior Trim	1-Methyl-2-pyrrolidone (872-50-4); 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol (3147-75-9); Bumetrizole (3896-11-5); C,C'-azodi(formamide) (123-77-3); Lead (7439-92-1); Lead titanium zirconium oxide (12626-81-2); Lead-monoxide (1317-36-8); Melamine (108-78-1); N,N-Dimethylacetamide (127-19-5); Triphenyl-phosphate (115-86-6)
Customer Switches, Keys	1,2-Dimethoxyethane (110-71-4); 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol (3147-75-9); 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one (71868-10-5); 4,4'-Isopropylidenediphenol (80-05-7); Bis(alpha,alpha-dimethylbenzyl) peroxide (80-43-3); Bumetrizole (3896-11-5); Lead (7439-92-1); Lead-monoxide (1317-36-8); Lead-titanium-trioxide (12060-00-3); Octamethylcyclotetrasiloxane (556-67-2)
Driver Information & Infotainment System	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol (3147-75-9); 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol (25973-55-1); 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone (119313-12-1); 2-ethylhexyl 10-ethyl-4,4-dioctyl-7-oxo-8-oxa-3,5-dithia-4-stannatetradecanoate (15571-58-1); 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one (71868-10-5); 4,4'-Isopropylidenediphenol (80-05-7); 4-Nonylphenol, branched (84852-15-3); 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol (119-47-1); Bis(2-ethylhexyl) tetrabromophthalate (26040-51-7); Bis(alpha,alpha-dimethylbenzyl) peroxide (80-43-3); Bumetrizole (3896-11-5); C,C'-azodi(formamide) (123-77-3); Cobalt(II) nitrate hexahydrate (10026-22-9); Decamethylcyclopentasiloxane (541-02-6); Diboron-trioxide (1303-86-2); Dioctyltin dilaurate (3648-18-8); Lead (7439-92-1); Lead-monoxide (1317-36-8); Lead-titanium-trioxide (12060-00-3); Melamine (108-78-1); N,N-Dimethylacetamide (127-19-5); Nonoxinol (9016-45-9); Octamethylcyclotetrasiloxane (556-67-2); Poly(oxy-1,2-ethanediyl), alpha-(nonylphenyl)-omega-hydroxy-, branched (68412-54-4)
Interior (Other)	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol (3147-75-9); 4,4'-Isopropylidenediphenol (80-05-7); Bis(alpha,alpha-dimethylbenzyl) peroxide (80-43-3); Bumetrizole (3896-11-5); C,C'-azodi(formamide) (123-77-3); Diboron-trioxide (1303-86-2); Lead (7439-92-1); Lead-monoxide (1317-36-8)

Body	
Controls	Bis(alpha,alpha-dimethylbenzyl) peroxide (80-43-3); Diboron-trioxide (1303-86-2); Lead (7439-92-1); Lead-monoxide (1317-36-8)
Powertrain, Cooling System, Chassis & Body, Battery System, Lighting – Parts without intended customer contact	1,2-Dimethoxyethane (110-71-4); 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6-(1H,3H,5H)-trione (2451-62-9); 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.1.6,9.0.2,13.0.5,10]octadeca-7,15-diene (13560-89-9); 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) (29420-49-3); 1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- (119344-86-4); 1-Methyl-2-pyrrolidone (872-50-4); 1-Propanol, 2,3-dibromo- (96-13-9); 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol (3147-75-9); 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol (25973-55-1); 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone (119313-12-1); 2-ethylhexyl 10-ethyl-4,4-dioctyl-7-oxo-8-oxa-3,5-dithia-4-stannatetradecanoate (15571-58-1); 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one (71868-10-5); 2-Methylimidazole (693-98-1); 4,4'-Isopropylidenediphenol (80-05-7); 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol (119-47-1); Acrylamide (79-06-1); Alkanes, C14-17, chloro (85535-85-9); Alkanes, C16-35, chloro (85049-26-9); Benzene-1,2,4-tricarboxylic acid 1,2-anhydride (552-30-7); Bis(2-(2-methoxyethoxy)ethyl)ether (143-24-8); Bis(4-chlorophenyl) sulfon (80-07-9); Bis(alpha,alpha-dimethylbenzyl) peroxide (80-43-3); Boric acid (10043-35-3); Bumetizole (3896-11-5); C,C'-azodi(formamide) (123-77-3); Cobalt sulphate (10124-43-3); Decamethylcyclopentasiloxane (541-02-6); Diboron-trioxide (1303-86-2); Dicyclohexyl-phthalate (84-61-7); Dioctyltin dilaurate (3648-18-8); Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide (75980-60-8); Disodium-octaborate (12008-41-2); Dodecamethylcyclohexasiloxane (540-97-6); Glycols, polyethylene, mono(p-(1,1,3,3-tetramethylbutyl)phenyl) ether (9002-93-1); Imidazolidine-2-thione (96-45-7); Lead (7439-92-1); Lead titanium zirconium oxide (12626-81-2); Lead(II,IV)-oxide (1314-41-6); Lead-monoxide (1317-36-8); Lead-titanium-trioxide (12060-00-3); Melamine (108-78-1); N,N-Dimethylacetamide (127-19-5); N,N-Dimethylformamide (68-12-2); Nonoxinol (9016-45-9); Nonylphenol (25154-52-3); Octamethylcyclotetrasiloxane (556-67-2); Refractory ceramic fibres (142844-00-6); Silicic acid, lead salt (11120-22-2); TBBA (79-94-7); Triphenyl-phosphate (115-86-6); Tris(2-methoxyethoxy)vinylsilane (1067-53-4); Tris(nonylphenyl)phosphite (26523-78-4)
The information provided in this document has been provided to the best of our knowledge and belief on the basis of the available data.	